

WA-I-511      Frame House

Mid-20th century

Hagerstown Vicinity

Private

The Frame House is a one and one-half story, three bay by two bay house on a concrete block foundation. It has an odd-shaped gable roof with the front side extending a greater depth than the rear. The front of the house has a central entrance with a window on each side and two gabled roofed dormer windows on the roof. The house has a rectangular floor plan. The date of construction appears to be mid-20th century.

DOE            yes            no

historic      Frame house

and/or common

street & number east side of Rt. 65, .1 mile south of the intersection with I-70 not for publication

city, town Hagerstown   x   vicinity of congressional district sixth

state Maryland county Washington

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## name

street & number telephone no.:

city, town state and zip code

courthouse, registry of deeds, etc.	Washington County Courthouse	liber
-------------------------------------	------------------------------	-------

street & number      Washington Street      folio

city, town	Hagerstown	state	Maryland
------------	------------	-------	----------

## 6. Representation in Existing Historical Surveys

tle

date \_\_\_\_\_ ☐ federal ☐ state ☐ county ☐ local

depository for survey records

city, town state

## 7. Description

Survey No. WA-I-491 511

### Condition

☐ excellent  
☐ good  
☐ fair

☐ deteriorated  
☐ ruins  
☐ unexposed

### Check one

☐ unaltered  
☐ altered

### Check one

☐ original site  
☐ moved      date of move \_\_\_\_\_

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a one and one-half story three bay by two bay house on a concrete block foundation. It has an odd-shaped gable roof with the front side extending a greater depth than the rear. The front of the house has a central entrance with a window on each side and two gabled roofed dormer windows on the roof. The house has a rectangular floor plan. The date of construction appears to be mid-20th century.

The frame house is located on the east side of Rt. 65, .1 mile south of the intersection with I-70. It is grouped with a number of houses on  $\frac{1}{4}$  to  $\frac{1}{2}$  acre lots in a short stretch along Rt. 65. These houses dating from the 1930s to the present time.

The most notable feature of this house is its shape being a small house but distinguished by its asymmetrical gable roof. It sits on a level tract of land and has a high concrete block foundation covered with cement. The entranceway is marked by a small gable hood roof supported by brackets which is the only ornamentation on the house. Six-over-six windows are in the other two bays on the front of the house and smaller six-over-six windows on the dormers on the roof. A small flue protrudes from a southern end of the gable roof. The exterior is covered in aluminum siding. The roof is asphalt shingle.

The property contains no significant outbuildings.

## 8. Significance

Survey No. WA-I-491 511

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

### Specific dates

### Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☐ C ☐ D  
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G


Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

Based on the MHT Survey Matrix, this is a minimal site due to its recent date of construction.




WA-I-511  
 Frame House, site  
 Sharpsburg Pike (MD 65)  
 Funkstown Quadrangle



1993-94 Aerial Photo

Tax Map 57, p. 157





1. Frame House      WA-I-491 5 //
2. Washington County, Maryland
3. Joe Getty
4. April 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. West Elevation; camera facing west
7. 1/1